

Technical Service Bulletin # 2

Product:	Babytherm 8000 OC
Date:	November 30, 1999
Re:	Bolts of attachment of shelf 2M 21 158
Reference Doc:	IDM no. 3 / 03.95
Reason:	If overtightened and in the case of repeated tightening (e.g. on subsequent alteration of shelf height) the 4 attachment bolts for the shelf 2M 21 158 (monitor mount) jam. That makes further adjustments impossible. Cause: Excessive gap between the two halves (1.3 mm). If an attempt is made on assembly to pull the two halves together, the torque for the bolts is too high and results in jamming in the thread pair.
Solution:	On assembly: Only tighten the 4 bolts to 5 Nm. This is sufficient to securely attach the shelf. In the event of this failure: Replace shelf.
Devices affected:	All Babytherm 8000 OC shipped prior to mid-1995.
When:	With next repair or replacement of shelf.
Additional Info:	N/A
Cost:	Covered by Customer, post warranty.
Ordering Info:	Shelf 2M 21 158
Distribution:	Dräger Service Personnel and Authorized Service Organizations for NCS products.

If you have any questions, please contact Technical Support by phone at 1-800-543-5047 or by fax at 1-215-723-5935

Dräger Medical, Inc.
Technical Product Manager

Andreas Lenke