

Babytherm 8000 Technical Service Bulletin # 11

Re: Mattress heating, replacing Controller PCB, new Software Version 1.04

Date: April 30, 2001

Reference Doc: Service Bulletin from Dräger Medizintechnik GmbH:
6132.200 Babytherm 8000 # 11, February 13, 2001

Reason: A new EEPROM on the Controller PCB P/N 8290668 requires the new software version 1.04. If a new Controller PCB is used with the previous software version error code 15 will be generated.

Solution: When replacing the PCB Controller P/N 8290668, software version 1.04 must be installed.

Devices affected: All units Babytherm 8000 with installed software version 1.02.

When: With next replacement of Controller PCB P/N 8290668.

Reporting: N/A

Additional Info: N/A

Cost: Covered by Customer, post warranty.

Ordering Info: EPROM SW1.04 Babytherm 8000 P/N 2M 22 467

Distribution: Dräger Service Personnel and Authorized Service Organizations.

If you have any questions, please contact Technical Support by phone at 1-800-543-5047 or by fax at 1-215-721-5789.

Dräger Medical, Inc.
Technical Product Manager